


NFC Box WL20 Quick Start Guide

1. Dimension (mm)




2. LED Indicator

Status	Description
Solid White	Work Normally
Flash White	Read Successfully

3. Deployment

- 1) Connect the NFC Box WL20 to the **USB 2.0** port at the bottom of the Display.
- 2) Attach the WL20 magnetically to the back of the Display.
- 3) Bring the card close to the WL20 to read the information.



4. Simple Troubleshooting

* **Communication Failure**

- a. Check if the reader is powered on properly (status indicator light is on).
- b. In Device Manager, check if the USB device is correctly recognized.
- c. Ensure the cables are connected correctly.

* **Electronic Tag Reading Failure**

- d. Check if the tested electronic tag protocol matches the protocol supported by the reader.
- e. Try with more tags of different models.
- f. Move the tag up and down within the working range.
- g. Check if there are any other materials covering the surface of the electronic tag.